

ANNEX 6.
PHOTOGRAPHS

Photo 1:	Sedimentation of Channel between Road and Ergio Prod Factory circa 2003.....	2
Photo 2:	Sedimentation of Channel Immediately above Ergio Prod Factory circa 2003	2
Photo 3:	Old Waste Dump from Below January 27, 2006.....	3
Photo 4:	Ergio Prod Factory with Mine Site in Background January 27, 2006.....	3
Photo 5:	Ergio Prod Factory seen from the Old Waste Dump February 1, 2006	4
Photo 6:	Material Removed from Channel February 1, 2006	4
Photo 7:	Material in Old Waste Dump February 1, 2006	5
Photo 8:	Photograph of Sign at Closure Site circa September 2002	5
Photo 9:	Picture of Waste Dump after Floods circa September 2005.....	6
Photo 10:	Photograph of Swale circa 2003	6
Photo 11:	Condition of Access Road February 1, 2006.....	7

Photographs

Photo 1: Sedimentation of Channel between Road and Ergio Prod Factory circa 2003



Photo 2: Sedimentation of Channel Immediately above Ergio Prod Factory circa 2003



Photo 3: Old Waste Dump from Below January 27, 2006




Photo 4: Ergio Prod Factory with Mine Site in Background January 27, 2006



Photo 5: Ergio Prod Factory Seen from the Old Waste Dump February 1, 2006



Photo 6: Material Removed from Channel February 1, 2006



Photo 7: Material in Old Waste Dump February 1, 2006



Photo 8: Photograph of Sign at Closure Site circa September 2002



Photo 9: Picture of Waste Dump after Floods circa September 2005



Photo 10: Photograph of Swale circa 2003



Photo 11: Condition of Access Road February 1, 2006

